

Steamstor specific changes

- * Upgraded the WinDriver to 9.21, which includes support for kernel version 2.6.24.
- * Fixed a bug in XLRPlaybackLoop that caused it to incorrectly report an out of range error.
- * Fixed a bug in XLROpen which resulted in a memory leak if it were called repeatedly within the same application program.

For the package installer itself

- * In the installation process, added into the prerm script the removal of the windrvr6 module from the kernel before the program compiling and installing the driver.